

THRAPSTON & DISTRICT TENNIS CLUB – RISK ASSESSMENT

This RA assesses the likely hazards to the safety of players on courts and visitors to the Club and ensures that the risks are reduced to as low as reasonably possible (ALARP).

| <b>Hazards</b>                        | <b>Measures Required</b>                                    | <b>Measures Taken</b>  | <b>By Whom</b>    | <b>Date</b> |
|---------------------------------------|---|--|-------------------|-------------|
| Spread of Corona Virus                | Adherence to guidance as published by the LTA.              | Members are notified by newsletter. Relevant notices are displayed around the Club.  | All               | May 21      |
| Injury to personnel on and off courts | Coaches generally have first aid training.                  | First aid equipment and a defibrillator are situated in the corridor inside the Clubhouse. An Accident Log is maintained and reviewed at cte meetings. | Coaches Committee | May 21      |
|                                       | Slip hazards due to ice during winter months.               | A supply of salt/grit is available to spread on approaching pathways when necessary. (Mainly intended for morning coaching sessions.)                  | Coaches           | May 21      |
|                                       | Trip hazards when walking to/from carpark.                  | Green Lane Clinic ensures that the car park lighting is serviceable and illuminated during darkness.   | All               | May 21      |
|                                       | Trip hazards when walking to/from the courts.               | Security lights outside the Clubhouse are sensor-operated to provide necessary illumination.   | All               | May 21      |
|                                       | Trip hazards on wooden decking.                             | Non-slip strips are fitted to steps and walkways where required.   | All               | May 21      |
|                                       | Slip hazard on disabled ramp.                               | Ramp is regularly swept to ensure firm grip.   | All               | A/R         |
| Legionella                            | Warm, stagnant water is a breeding ground for this disease. | All taps and showerheads are flushed-through once a month during periods of low activity in the winter.  | Committee         | A/R         |

Updated: 17 May 21